



WIRING DIAGRAM
SCREW LUG TERMINALS OR LEADS

PRIMARY
FRONT VIEW

25VA – 200VA


250VA – 7500VA



SECONDARY
FRONT VIEW

25VA – 200VA

250VA – 7500VA



LOWEST OF 2 VOLTAGES




HIGHEST OF 2 VOLTAGES

TAP

PARALLEL

SERIES

DO / DL / DC
BLACK / NOIR
RED / ROUGE
WHITE / BLANC



CONNECT

JOIN

JOIN

LOW
H1 – H2
HIGH
H1 – H3

H4–H2 & H3–H1
CONNECT
H1 – H4

H2 – H3
CONNECT
H1 – H4



LOWEST OF 2 VOLTAGES

HIGHEST OF 2 VOLTAGES

PARALLEL

SERIES

H OR / O B X
DO / DL / DC
BLACK / NOIR
RED / ROUGE
BLACK / NOIR
RED / ROUGE



JOIN

JOIN

X4–X2 & X3–X1
CONNECT
X1 – X4

X2 – X3
CONNECT
X1 – X4